

Oil Field Environmental Incident Summary

Incident: 20151029184815 **Date/Time of Notice:** 10/29/2015 18:48

Responsible Party: Crescent Point Energy U.S. Corp

Well Operator: CRESCENT POINT ENERGY U.S. CORP.

Well Name: 2-BRENDEN 9-33 1-M

Field Name: NORTH SOURIS

Well File #: 24883

Date Incident: 10/29/2015 **Time Incident:** 10:15

Facility ID Number:

County: BOTTINEAU

Twp: 164

Rng: 77

Sec: 33

Qtr:

Location Description: Well site

Submitted By: Chris Del Hierro

Received By:

Contact Person: Scott Van De Woestyne
555 17th Street, Suite 1800
Denver, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	30	Barrels	28	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Within dike

Potential Environmental Impacts:

soil within dike

Action Taken or Planned:

Pipe to be repaired, water recovered via vac truck, impacted soil to be excavated.

Wastes Disposal Location: Recovered water placed back into tanks. Excavated soil to be placed in waste storage bins until volume and appropriate disposal facility identified.

Agencies Involved:

Updates

Date: 10/30/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pipeline leak, remained on location according to the report. NDIC retains oversight.